

I. Specifications:

Working temperature: -20-60°C

Product size: L50 × W35 × H22mm

Output: Three CMOS drain- open output

Package size: L106 × W64 × H56mm

Max load current: 2 A each color

Net weight: 46.5g

Gross weight:71g

II. Control Method:

Adopt IR remoter to control the led controller, which has 24 buttons, the function of each button as the table below:

Brightness +(16 in all)	Brightness-(16 in all)	Off	On
Static red	Static green	Static blue	Static white
Static orange	Static pea green	Static dark blue	7 color jumpy change
Static dark yellow	Static cyan	Static brown	All fade out & fade in
Static yellow	Static light blue	Static pink	7 color fade change
Static straw yellow	Static sky blue	Static purple	3 base color jumpy

Direction: press static color every time, the matching mode flicker two times before stopping, then recover the static color, When switching to four dynamic mode (7 color jumpy change, All fade out & fade in , 7 color fade change, 3 base color jumpy), the button of "Brightness + / "Brightness-" means the speed of linht change is up/ down, there are 32 step in all.

I. Specifications:

Working temperature: -20-60°C

Product size: L50 × W35 × H22mm

Output: Three CMOS drain- open output

Package size: L106 × W64 × H56mm

Max load current: 2 A each color

Net weight: 46.5g

Gross weight:71g

II. Control Method:

Adopt IR remoter to control the led controller, which has 24 buttons, the function of each button as the table below:

Brightness +(16 in all)	Brightness-(16 in all)	Off	On
Static red	Static green	Static blue	Static white
Static orange	Static pea green	Static dark blue	7 color jumpy change
Static dark yellow	Static cyan	Static brown	All fade out & fade in
Static yellow	Static light blue	Static pink	7 color fade change
Static straw yellow	Static sky blue	Static purple	3 base color jumpy

Direction: press static color every time, the matching mode flicker two times before stopping, then recover the static color, When switching to four dynamic mode (7 color jumpy change, All fade out & fade in , 7 color fade change, 3 base color jumpy), the button of "Brightness + / "Brightness-" means the speed of linht change is up/ down, there are 32 step in all.